

Product Recalls

►Water Pump Electric Motors_

Description: The recall involves motors included with lawn sprinkler pumps and jet pumps manufactured by F. E. Myers Co. The recall also includes replacement pump motors that were sold separately.

- QP10 -- Lawn Sprinkler Pump
 - QP10B -- Lawn Sprinkler Pump with Brass Impeller
 - HJ100S -- Shallow Well Jet Pump
- HJ100S-K -- Shallow Well Jet Pump (Canada Distribution)
- HJ100S-1 -- Shallow Well Jet Pump with Brass Impeller
 - HJ100D -- Deep Well Jet Pump
 - HJ100D-LR -- Deep Well Jet Pump Less Regulator
- HJ100D-K -- Deep Well Jet Pump (Canada Distribution)
- HJ100D-1 -- Deep Well Jet Pump with Brass Impeller
- 20935A000K -- Individually Sold Replacement Motor

Only pumps manufactured between August 2007 and May 2008 are included in the recall. The pump's model number, manufacturing date code and the name "Myers" can be located on the pump's nameplate and packaging. The pump's motor has "A. O. Smith" and model number "C48D52B86" on the motor's nameplate. The replacement motor's packaging has "Myers" and model number "20935A000K" printed on it. Products with an "OK" sticker on the product or packaging are not included in the recall.

►Exhaust Fan Electric Motors_

Description: The recalled electric motor is part of a residential whole-house exhaust fan that is typically mounted on the floor of an attic. The shutters of the fan are visible on the ceiling of the floor beneath the attic and must be opened and closed by the consumer. The motors were included with exhaust fans manufactured and distributed by Air Vent Inc. and Triangle Engineering of Arkansas Inc. "A.O. Smith," the model number, and the service date code are printed on the rating plate of the motor. The recall includes model numbers S56A30A54 and S56A30A97, and service date codes 032076M - 334076M, 03207JY - 33407JY, and YB07 - YL07. Units that have a sticker indicating that the unit has been rewired are not subject to this recall.